



# STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

|                              |  |                        |  |
|------------------------------|--|------------------------|--|
| Project Name:                | Mountain Valley Pipeline                                   | S&S Program:           | Mountain Valley Pipeline (SS027)                                   |
| Inspector:                   | Marshall Willis  | Inspection Date:       | Wednesday, July 31, 2024   |
| Project Contact:             | Cory Chalmers<br>Brian Clauto                              | Project Contact Email: | cchalmers@equitransmidstream.com<br>bclauto@equitransmidstream.com |
| Spread I:<br>Franklin County | STA 14272+62 – STA 14345+53<br>MVP-FR-313<br>MVP-FR-313.01 | Site Conditions:       | Dry  |

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling      ☐ Clearing/Grubbing      ☐ Rough Grading      ☐ Trenching      ☐ Stringing/Welding  
☐ Lowering/Backfilling      ☐ Final Grading      ☐ Temp. Stabilization      ☒ Perm. Stabilization      ☐ Other

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-F9B, S-F9A, S-GG4 and S-A36.

Corrective Action: N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Wednesday, July 31, 2024

# STANDARDS & SPECIFICATIONS

## SITE INSPECTION REPORT

### LEVEL 1 (FIELD REPORT)

### FIELD INSPECTION PHOTO LOG

Fig. 1

**STA 14286+00:** Controls in place and functioning properly.

☉ 131°SE (T) LAT: 37.048610 LON: -79.814859 ±39ft ▲ 952ft



Fig. 2

**STA 14292+00:** Controls in place and functioning properly.

☉ 160°S (T) LAT: 37.047454 LON: -79.813102 ±19ft ▲ 1016ft



Fig. 3

**STA 14304+00:** Controls in place and functioning properly.

☉ 159°S (T) LAT: 37.044871 LON: -79.811243 ±9ft ▲ 1079ft



Fig. 4

**STA 14329+00:** Controls in place and functioning properly.

☉ 339°N (T) LAT: 37.039865 LON: -79.805817 ±65ft ▲ 1160ft

