

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Matthew Grant	Inspection Date:	Wednesday, August 14, 2024
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com
Spread I: Franklin County	STA 13648-13748, 13788 ATWS 569A, 1067, 1261, 1262, MLV 30 FR 300	Site Conditions:	Dry

ACTI	CTIVE STAGE OF CONSTRUCTION: (Check all that apply)														
	Tree Felling			☐ Clearing/Grubbing		Rough Grading		Trenching		Stri	nging/Welding				
	Lowering/Backfilling			Final Grading		Temp. Stabilization		Perm. Stabilization		Dor	rmant				
									Yes	No	N/A				
	 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? 								\boxtimes						
									\boxtimes						
	Areas of offsite sediment deposition observed?								\boxtimes						
	Comments: Inspected the following resources: S-E28 Routine Maintenance: (72-Hour Deadline from Notification) - N/A Ineffective Controls: (24-Hour Deadline from Notification) - N/A														
	Correc	tive Actio	<u>on:</u> N	N/A											

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Palt in How



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1
Description: Designated Crossing S-E28, ECD's are in place.



Fig. 2 Description: Sta 13748, ECD's are in place.



Fig. 3 Description: Sta 13788, ECD's are in place.



Fig. 4 Description: FR300, ECD's remain in place.

