

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)			
Inspector:	Marshall Willis	Inspection Date:	Thursday, August 29, 2024			
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com			
Spread I: Pittslyvania County Franklin County	STA 14692+00 - STA 14705+00 STA 15113+00 - STA 15142+66	Site Conditions:	Dry			

ACT	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling			Clearing/Grubbing		Rough Grading		Trenching		Stri	nging/Welding			
	Lowering/Backfilling			Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization	n 🗌 Other		ner			
									Yes	No	N/A			
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes					
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes					
	3. Areas of offsite sediment deposition observed?									\boxtimes				
	Comments: Inspected the following resources: S-H32, S-A5, S-A6 and S-H11. Routine Maintenance: (72-Hour Deadline from Notification) - STA 14698+00 to 14699+00: Restabilize area as needed. - STA 15136+00 to 15139+00: Restabilize area as needed.													
	Corrective Action: Maintain and install all controls per the approved S&S.													

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Thursday, August 29, 2024



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 **STA 14698+00 to 14699+00:** Restabilize area as needed.



Fig. 2 **STA 15136+00 to 15139+00:** Restabilize area as needed.



Fig. 3 **STA 15130+00:** Controls in place and functioning properly.



Fig. 4

STA 15143+00: Controls in place and functioning properly.

