

## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Matthew Grant	Inspection Date:	Tuesday, September 10, 2024
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com
Spread G:	STA 10858-10930	Site Conditions:	Dry

	☐ Tree Felling		<b>FRUCTION:</b> (Check all that ☐ Clearing/Grubbing		☐ Rough Grading		☐ Trenching			Stri	nging/Welding
	Lowering/Backfilling			Final Grading		Temp. Stabilization	$\boxtimes$	Perm. Stabilization	ı 🗵	Dor	rmant
									Yes	No	N/A
	<ol> <li>Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?</li> <li>Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?</li> </ol>								$\boxtimes$		
										$\boxtimes$	
	Areas of offsite sediment deposition observed?								$\boxtimes$		
	Routin	e Maintena Sta 1087	ince: 74+0(	he following resources ( <u>72-Hour Deadline</u> fro ) – 10874+50 requin 24-Hour Deadline from	m Noti e re-s	ification) tabilization of denude	ed so	ils.			
	Correc	ctive Actio	on: N	/laintain and install a	ıll con	trols per the approve	ed S&	S.			

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

## FIELD INSPECTION PHOTO LOG

Fig. 1
Description: Designated Crossing S-Y3, ESC is in place.



Fig. 2
Description: Designated Crossing S-Y2, ESC is in place.



Fig. 3
Description: Designated crossing S-G32, ESC is in place.



Fig. 4
Description: Sta 10874-10874+50 requires additional stabilization of denuded soils.

