

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Wednesday, September 11, 2024
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com
Spread I: Franklin County	STA 14333+27 - STA 14411+04 STA 13425+01 - STA 13437+00 STA 14009+86 - STA 14018+58 MVP-FR-306.02	Site Conditions:	Dry

<u>ACTI</u>	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling			Clearing/Grubbing		Rough Grading		Trenching		Stri	nging/Welding			
	Lowering/E	ring/Backfilling		Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization		Oth	ner			
									Yes	No	N/A			
	1.	1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?												
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes				
	3. Areas of offsite sediment deposition observed?									\boxtimes				
 <u>Comments:</u> Inspected the following resources: S-A36, S-A41, S-A38 and W-DD1. Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) STA 14334+00 to 14337+00: Restabilize as needed. <u>Corrective Action:</u> Maintain and install all controls per the approved S&S. 														

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Wednesday, September 11, 2024



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 **STA 14334+00 to 14337+00:** Restabilize as needed.



Fig. 2 **Stream S-A41:** Controls in place and functioning properly.



Fig. 3 **STA 14017+00:** Controls in place and functioning properly.



Fig. 4
STA 13425+00: Controls in place and functioning properly.

