

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Tuesday, September 10, 2024
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com
Spread H: Franklin County	STA 13012+63 - STA 13040+00 MVP-FR-289 MVP-FR-290	Site Conditions:	Dry

ACTI	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling		☐ Clearing/Grubbing			Rough Grading		Trenching		Stri	nging/Welding			
	Lowering/B	ackfilling		Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization	n 🗌 Other					
									Yes	No	N/A			
	1.	1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes				
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes					
	3. Areas of offsite sediment deposition observed?								\boxtimes					
Comments: Inspected the following resources: W-ST2-PEM, S-G24, S-G25 and S-RR16. Ineffective Controls: (24-Hour Deadline from Notification) - Stream S-RR16: Properly install erosion control matting along Stream S-RR16 on MVP-FR-290. Corrective Action: Maintain and install all controls per the approved S&S.														

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Tuesday, September 10, 2024



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 Stream S-RR16: Properly install ECM.



Fig. 2 MVP-FR-290: Controls in place and functioning properly.



Fig. 3 **STA 13028+00:** Controls in place and functioning properly.



Fig. 4

MVP-FR-289: Controls in place and functioning properly.

