

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Matthew Grant	Inspection Date:	Thursday, October 17, 2024
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com
Spread G: Giles County	Sta 11298-11354 ATWS 633, 633A GI 256	Site Conditions:	Dry

	CTIVE STAGE OF CONSTRUCTION: (Check all that apply)														
	Tree Felling		Ш	Clearing/Grubbing	Ш	Rough Grading		Trenching	Ш	Stri	nging/Welding				
	Lowering/Back	ng/Backfilling \square Final Grading \square Temp. Stabilization $oxtimes$ Perm. Stabilizati		Perm. Stabilization		Oth	ner								
									Yes	No	N/A				
	 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? 								\boxtimes						
										\boxtimes					
	3. Are	eas of of	fsite s	sediment deposition o	bserve	ed?				\boxtimes					
	<u>Comments:</u> Designated resource crossing include: S-NN12, S-NN11														
	Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - Designated Stream S-NN11, repair bed and banks of stream.														
		e Contro //A	ols: (<u>2</u>	4-Hour Deadline fron	n Notifi	cation)									
	Corrective Action: Maintain and install all controls per the approved S&S.														

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1
Description: Designated Stream S-NN12, ESC is in place.



Fig. 2
Description: Designated Stream S-NN11, bed and banks of stream require repair.




Fig. 3 Description: Sta 11323, ESC is in place.



Fig. 4
Description: AR GI 256, ESC remains in place.

