

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)			
Inspector:	Marshall Willis	Inspection Date:	Monday, November 4, 2024			
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com			
Spread I: Franklin County	STA 13748+30 - STA 13811+81	Site Conditions:	Dry			

ACT	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling		☐ Clearing/Grubbing			Rough Grading		Trenching		Stringing/Welding				
	Lowering/Backfilling			Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization		Oth	er			
									Yes	No	N/A			
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes					
	2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?									\boxtimes				
	3. Areas of offsite sediment deposition observed?									\boxtimes				
	Comments: Inspected the following resources: S-EF7, S-EF42, S-MM42, S-RR15, S-D23, S-D22 and S-D20. Routine Maintenance: (72-Hour Deadline from Notification) - STA 13810+00: Restabilize area. Corrective Action: Maintain and install all controls per the approved S&S.													

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Monday, November 4, 2024 Date:



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 **Stream S-EF12:** Controls in place and functioning properly.



Fig. 2 **STA 13785+00:** Controls in place and functioning properly.



Fig. 3 **STA 13792+00:** Controls in place and functioning properly.



Fig. 4
STA 13810+00: Restabilization required.

