

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Matthew Grant	Inspection Date:	Wednesday, November 13, 2024
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	brian.clauto@eqt.com cory.chalmers@eqt.com
Spread G: Montgomery County	Sta 11670-11767+44 MLV 26	Site Conditions:	Wet

ACT	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling		Clearing/Grubbing	ı 🗆	Rough Grading		Trenching		Stri	nging/Welding				
	Lowering/Backfill	ing \square	Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization	n 🗵 Dormant		rmant				
								Yes	No	N/A				
	 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? 													
									\boxtimes					
	3. Areas	s of offsite	sediment deposition	n observe	ed?				\boxtimes					
	Comments: Designated resource crossing inspected included: S-MN21, S-MN22, S-EF65, S-EF62, S-IJ52 ECD's remain in place at crossings. Routine Maintenance: (72-Hour Deadline from Notification) - Sta 11679+80, silt fence has hole and requires repair. Ineffective Controls: (24-Hour Deadline from Notification) - N/A Corrective Action: Maintain and install all controls per the approved S&S.													

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1

place.

Description: Sta 11679+80 silt fence has hole.



Fig. 3
Description: Designated stream S-MN22, ESC remains in



Fig. 2
Description: Designated Stream S-MN21, ECD's remain in place.




Fig. 4
Description: Designated stream S-IJ 52, ESC remains in place.

