



# STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

|                                |  |                        |   |
|--------------------------------|--|------------------------|---|
| Project Name:                  | Mountain Valley Pipeline                         | S&S Program:           | Mountain Valley Pipeline (SS027)              |
| Inspector:                     | Matthew Grant                                    | Inspection Date:       | Wednesday, November 13, 2024                  |
| Project Contact:               | Cory Chalmers<br>Brian Clauto                    | Project Contact Email: | brian.clauto@eqt.com<br>cory.chalmers@eqt.com |
| Spread G:<br>Montgomery County | Sta 11614+20-11600, 11979<br>ATWS 1057<br>MN 266 | Site Conditions:       | Dry   |

## ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling      ☐ Clearing/Grubbing      ☐ Rough Grading      ☐ Trenching      ☐ Stringing/Welding  
☐ Lowering/Backfilling      ☐ Final Grading      ☐ Temp. Stabilization      ☒ Perm. Stabilization      ☒ Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Designated resource crossing inspected included: S-RR13, S-RR14, S-006  
ECD's remain in place at crossings.

### Routine Maintenance: (72-Hour Deadline from Notification)

- N/A

### Ineffective Controls: (24-Hour Deadline from Notification)

- N/A

### Corrective Action: N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

# STANDARDS & SPECIFICATIONS

## SITE INSPECTION REPORT

### LEVEL 1 (FIELD REPORT)

### INSPECTION PHOTO LOG

FIELD

Fig. 1

Description: Designated Stream S-006, ECD's remain in place.



Fig. 2

Description: Designated Stream S-RR13, ECD's remain in place.



Fig. 3

Description: Designated stream S-RR14, ESC remains in place.



Fig. 4

Description: Sta 11979, ESC remains in place.

