

## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

**LEVEL 1 (FIELD REPORT)** 

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis, Matthew Grant, Zack Robinson, John McCutcheon	Inspection Date:	Wednesday, December 11, 2024
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com
Spread I: Franklin County Pittslyvania County	MVP-MLV-AR-32 MVP-MLV-AR-33 MVP-MLV-AR-34 STA 14223+00 – 14249+00	Site Conditions:	Rainy

ACTI	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling		☐ Clearing/Grubbing			☐ Rough Grading		☐ Trenching		Stri	inging/Welding			
	Lowering/Backfilling			Final Grading		Temp. Stabilization	$\boxtimes$	Perm. Stabilization	on $\square$ Oth		ner			
									Yes	No	N/A			
	1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								$\boxtimes$					
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?									$\boxtimes$				
	3. Areas of offsite sediment deposition observed?									$\boxtimes$				
Comments: Inspected the following resources: S-C19 and S-F11.  Maintenance Issues:  - STA 14232+00: CFS cleanout/maintenance (24-hr)  - STA 14232+00: Repair and restabilize area (72-hr)  - STA 14231+00: Repair perm. WB (72-hr)  Corrective Action: Maintain and install all controls per the approved S&S.														

**Deadline:** Various - See Comments

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

Date: Wednesday, December 11, 2024



## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

## FIELD INSPECTION PHOTO LOG

Fig. 1 STA 14231+00: Perm. WB sloughing.



Fig. 2 STA 14232+00: Erosion occurring above S-C19.



Fig. 3 **STA 14232+00:** CFS full above S-C19.



Fig. 3 **STA 14232+00:** CFS full above S-C19.

