

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)			
Inspector:	Marshall Willis	Inspection Date:	Wednesday, November 20, 2024			
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com Wet			
Spread H: Franklin County	STA 12807+43 - STA 12866+36 MVP-RO-283	Site Conditions:				

ACT	CTIVE STAGE OF CONSTRUCTION: (Check all that apply)														
	Tree Felling			Clearing/Grubbing		Rough Grading		Trenching		Stri	nging/Welding				
	Lowering/B	/Backfilling \square Final Grading \square Temp. Stabilization $oxtimes$ Perm. Stabilizati		Perm. Stabilization		Other									
									Yes	No	N/A				
	1.	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?													
	2.	2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes					
	3. Areas of offsite sediment deposition observed?									\boxtimes					
	Comments: Inspected the following resources: S-IJ89, S-IJ90, W-KL17, S-KL25, W-AB6 and W-AB5. Routine Maintenance: (72-Hour Deadline from Notification) - STA 12808+00 to 12825+00: Consolidate construction materials. - STA 12835+00: Remove debris from damaged wattles. Corrective Action: Remove and properly dispose of construction debris.														

<u>Deadline:</u> Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Wednesday, November 20, 2024



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 STA 12808+00: Consolidate construction materials.



Fig. 2 STA 12815+00: Consolidate construction materials.



Fig. 3 **STA 12820+00:** Consolidate construction materials.



Fig. 4 STA 12835+00: Remove damage wattles and debris.

