

## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

**LEVEL 1 (FIELD REPORT)** 

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)			
Inspector:	Marshall Willis	Inspection Date:	Monday, December 23, 2024			
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com			
Spread I: Franklin County	STA 13435+00 - 13450+00 STA 13540+00 - 13543+00 STA 13562+63 - 13575+21 MVP-FR-293.02	Site Conditions:	Frozen			

CTI	CTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling	9		Clearing/Grubbing		Rough Grading		Trenching		Stri	nging/Weldin			
	Lowering/B	ing/Backfilling $\square$ Final Grading $\square$ Temp. Stabilization $oxtimes$ Perm. Stabilizatio			Dor	rmant								
									Yes	No	N/A			
	1.	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							$\boxtimes$					
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							$\boxtimes$						
	3.	Areas of of	fsite	sediment deposition of	serve	d?				$\boxtimes$				
				-		3, S-II9, S-GH6 and W-	GH2.							
	Routing	e Maintena N/A	nce:	( <u>72-Hour Deadline</u> fro	m Noti	tication)								
	Ineffec	tive Contro N/A	ols: ( <u>2</u>	<u>24-Hour Deadline</u> from	Notific	cation)								
	Correc	ctive Actio	<u>on:</u> №	I/A										

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

Date: Monday, December 23, 2024



## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

## FIELD INSPECTION PHOTO LOG

Fig. 1

STA 13438+00: Controls in place and functioning properly.



Fig. 2 **Stream S-II9:** Controls in place and functioning properly.



Fig. 3 **STA 13718+00:** Controls in place and functioning properly.



Fig. 4 STA 13575+00: Controls in place and functioning properly.

