

## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

**LEVEL 1 (FIELD REPORT)** 

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)			
Inspector:	Marshall Willis	Inspection Date:	Tuesday, December 17, 2024			
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com			
Spread I: Franklin County	STA 13644+82 - 13748+30	Site Conditions:	Wet			

CT	CTIVE STAGE OF CONSTRUCTION: (Check all that apply)														
	Tree Felling		☐ Clearing/Grubbing			☐ Rough Grading		☐ Trenching		Stri	inging/Weldin				
	Lowering/B	Backfilling		Final Grading		Temp. Stabilization	$\boxtimes$	Perm. Stabilization		Doi	rmant				
									Yes	No	N/A				
	1.	<ol> <li>Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?</li> <li>Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?</li> </ol>													
	2.														
	<ol> <li>Areas of offsite sediment deposition observed?</li> </ol>								$\boxtimes$						
	Comments: Inspected the following resources: S-GH3, S-GH2, S-E29, S-E28, W-E4, W-E7 and S-EF4.  Routine Maintenance: (72-Hour Deadline from Notification) - N/A  Ineffective Controls: (24-Hour Deadline from Notification) - N/A														
	Correc	ctive Action	<u>on:</u> N	N/A											

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

Date: Tuesday, December 17, 2024



## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

**FIELD** 

## **INSPECTION PHOTO LOG**

Fig. 1

**STA 13645+00:** Controls in place and functioning properly.



Fig. 2 **STA 13681+00:** Controls in place and functioning properly.



Fig. 3 **STA 13718+00:** Controls in place and functioning properly.



Fig. 4 STA 13727+00: Controls in place and functioning properly.

