

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)			
Inspector:	Marshall Willis	Inspection Date:	Monday, December 16, 2024			
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com			
Spread H: Franklin County	STA 13140+00 - 13197+55 MVP-FR-292 MVP-FR-292.01	Site Conditions:	Rainy			

ACT	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling		☐ Clearing/Grubbing			Rough Grading		Trenching		Stri	nging/Welding			
	Lowering/Backfilling			Final Grading		Temp. Stabilization	on 🗵 Perm. Stabilizatio		n 🗵	Dormant				
									Yes	No	N/A			
	 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? 								\boxtimes					
									\boxtimes					
	3.	Areas of of	fsite	sediment deposition ob	serve	d?				\boxtimes				
	Routin - Ineffec	e M aintena N/A	nce: ols: (<u>⁄</u>	(<u>72-Hour Deadline</u> fron <u>24-Hour Deadline</u> from	n Not	,	3 and	S-D10.						

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Monday, December 16, 2024



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1

STA 13137+00: Controls in place and functioning properly.



Fig. 2 **Stream S-D11:** Controls in place and functioning properly.



Fig. 3 **STA 13163+00:** Controls in place and functioning properly.



Fig. 4
STA 13188+00: Controls in place and functioning properly.

