

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Matthew Grant	Inspection Date:	Monday, January 27, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	brian.clauto@eqt.com cory.chalmers@eqt.com
Spread G: Giles County Craig County	Sta 10975+68-1092+68, 10880, 10802+44, 11158+59 ATWS 1331, 471, 464 GI 241.02	Site Conditions:	Dry

ACT	CTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling			☐ Clearing/Grubbing ☐ Rough Grading ☐ Trenching		Trenching		Stri	nging/Welding					
	Lowering/Backfilling			Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization	n 🗵	Dor	rmant			
									Yes	No	N/A			
	 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? 								\boxtimes					
									\boxtimes					
	3. Areas of offsite sediment deposition observed?								\boxtimes					
	<u>Comments:</u> Designated resource crossing inspected included: S-Y2, S-Y3, S-A32, S-G35, S-Z13, S-NN17 ECD's remain in place at crossings. Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - N/A													
	Corre	ctive Actio	<u>on:</u> N	N/A										

Deadline: N/A

Date:

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Monday, January 27, 2025



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 Sta 10975: ECD's remain in place.



Fig. 2 Sta 10930: Roadside ditch is stabilized and controls remain in place.



Fig. 3
Designated stream S-A32, ESC remains in place.



Fig. 4
Sta 10965+75, Karsts feature remains protected ESC remains in place.

