

## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1	(FIELD	REPORT)
---------	--------	---------

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Friday, March 7, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	Cory.chalmers@eqt.com Brian.clauto@eqt.com
Spread H: Franklin County	STA 13140+00 - 13197+55 MVP-FR-292 MVP-FR-292.01	Site Conditions:	Wet

ACT	CTIVE STAGE OF CONSTRUCTION: (Check all that apply)										
	Tree Felling			☐ Clearing/Grubbing		☐ Rough Grading		☐ Trenching		Stri	nging/Welding
	Lowering/E	wering/Backfilling $\square$ Final Grading $\square$ Temp. Stabilization $oxtimes$ Perm. Stabilization			$\boxtimes$	Other					
									Yes	No	N/A
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							$\boxtimes$			
	2.	2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							$\boxtimes$		
	3.	Areas of o	ffsite	sediment deposition ob	serve	d?				$\boxtimes$	
	Routin -	ne Maintena MVP-FR-	a <b>nce:</b> 292: (	he following resources: ( <u>72-Hour Deadline</u> from CFS maintenance requ	n Noti ired.	ification)					
	Corre	ctive Actio	<u>on:</u> N	Aaintain and install a	ll con	trols per the approve	d S&	S.			

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

Date: Friday, March 7, 2025



## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

## FIELD INSPECTION PHOTO LOG

Fig. 1 MVP-FR-292: CFS maintenance required.



Fig. 2 **STA 13143+00:** Controls in place and functioning properly.



Fig. 3

Stream S-D11: Controls in place and functioning properly.



Fig. 4
STA 13188+00: Controls in place and functioning properly.

