

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Thursday, February 27, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@eqt.com bclauto@eqt.com
Spread I: Franklin County	STA 13784+35 - 13826+95 MVP-FR-300 MVP-FR-302	Site Conditions:	Dry

ACTI	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Fellin	g		Clearing/Grubbing		Rough Grading		Trenching		Stri	nging/Welding			
	Lowering/Backfilling 🗵 Final Grading 🗆 Temp. Stabilization			Perm. Stabilization		Res	source Crossin							
									Yes	No	N/A			
	1.	 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? 							\boxtimes					
	2.									\boxtimes				
	3.	Areas of of	ffsite	sediment deposition ob	serve	d?				\boxtimes				
	Routin	ne Maintena STA 1378	i nce: 39+00	he following resources: (72-Hour Deadline from: CFS undermined.	n Noti	ification)								
	Ineffec	ctive Contro N/A	ols: (<u>2</u>	<u>24-Hour Deadline</u> from	Notifi	cation)								
	Corre	ctive Actio	<u>on:</u> 1	N/A										

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Thursday, February 27, 2025



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 **STA 13789+00:** CFS undermined.



Fig. 2 **Stream S-D23:** Controls in place and functioning properly.



Fig. 3 **STA 13800+00:** Controls in place and functioning properly.



Fig. 4
STA 13813+00: Controls in place and functioning properly.

