

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)			
Inspector:	Marshall Willis	Inspection Date:	Friday, March 14, 2025			
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	Cory.chalmers@eqt.com Brian.clauto@eqt.com			
Spread I: Franklin County	STA 14345+53 - 14454+42 MVP-FR-313.01	Site Conditions:	Dry			

ACT	CTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling		☐ Clearing/Grubbing			☐ Rough Grading		☐ Trenching		Stri	nging/Welding			
	Lowering/Backfilling			Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization	n 🗆	Oth	er			
									Yes	No	N/A			
	1.	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?												
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?									\boxtimes				
	3. Areas of offsite sediment deposition observed?								\boxtimes					
Comments: Inspected the following resources: S-A38, W-DD1, S-A41, S-GH37, S-GH39, S-GH40, S-GH44 and W-GH Routine Maintenance: (72-Hour Deadline from Notification) - STA 14420+00: Repair undermined CFS. Ineffective Controls: (24-Hour Deadline from Notification) - N/A Corrective Action: Maintain and install all controls per the approved S&S.											V-GH46.			

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Friday, March 14, 2025



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 **STA 14420+00:** CFS undermined.



Fig. 2 **STA 14351+00:** Controls in place and functioning properly.



Fig. 3 **STA 14402+00:** Controls in place and functioning properly.



Fig. 4
STA 14450+00: Controls in place and functioning properly.

