



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Thursday, March 13, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	Cory.Chalmers@eqt.com Brian.Clauto@eqt.com
Spread H: Roanoke County	STA 12776+00 – 12807+43 MVP-RO-282 MVP-RO-283	Site Conditions:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling ☐ Clearing/Grubbing ☐ Rough Grading ☐ Trenching ☐ Stringing/Welding
☐ Lowering/Backfilling ☐ Final Grading ☐ Temp. Stabilization ☒ Perm. Stabilization ☐ Other

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-EF33, S-IJ82, W-IJ94-PEM, S-IJ83, S-IJ84, S-IJ88 and W-IJ95.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 12784+00 to 12785+00: Re-stabilize and repair denuded areas.


Ineffective Controls: (24-Hour Deadline from Notification)

- N/A

Corrective Action: Maintain and install all controls per the approved S&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Thursday, March 13, 2025

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1

STA 12784+00 to 12785+00: Repair and restabilize denuded areas.



Fig. 2

STA 12760+00: Controls in place and functioning properly.



Fig. 3

Stream S-IJ88: Controls in place and functioning properly.



Fig. 4

MVP-RO-283: Controls in place and functioning properly.

