

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

| Project Name: | Mountain Valley Pipeline | S&S Program: | Mountain Valley Pipeline (SS027) |
|--------------------------------|--|------------------------|---|
| Inspector: | Marshall Willis | Inspection Date: | Thursday, March 27, 2025 |
| Project Contact: | Cory Chalmers Brian Clauto | Project Contact Email: | Cory.chalmers@eqt.com Brian.clauto@eqt.com |
| Spread H: Montgomery County | STA 12416+00 - 12483+00 MVP-MN279/279.01 MVP-MLV-AR-28 | Site Conditions: | Dry |

| Т | ree Felling | g | | Clearing/Grubbing | | Rough Grading | | Trenching | | Str | inging/Welding |
|---|-------------|--|---|--|---------------------------------------|--|-------------|---------------------|-------------|-------------|----------------|
| L | owering/B | Backfilling | | Final Grading | | Temp. Stabilization | \boxtimes | Perm. Stabilization | \boxtimes | Do | rmant |
| | | | | | | | | | Yes | No | N/A |
| | 1. | | | alled and implemente I plan and stormwater | | cordance with the app gement plans? | roved | erosion and | \boxtimes | | |
| | 2. | | | | | I in effective operating applicable, manufactu | | | | \boxtimes | |
| | 3. | Areas of o | ffsite s | sediment deposition o | bserve | d? | | | | \boxtimes | |
| | Comme | ents: Inspe | cted t | he following resources | s: S-NN | N16, S-CD12b and W- | KL48. | | | | |
| | Routing | e Maintena STA 1242 STA 1242 STA 1242 Stive Contro | ince: 20+00 20+50 23+00 ols: (<u>2</u> | (72-Hour Deadline from to 12421+00: Repair : CFS maintenance noted to 12426+00: Repair : Repa | om Noti erosio eeded. erosio | <i>ification</i>) n and restabilize denu n and restabilize denu | ded ai | eas. | | | |

constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Thursday, March 27, 2025



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1

STA 12420+00 to 12421+00: Repair and restabilize denuded areas.



Fig. 2

STA 12420+00 to 12421+00: Repair and restabilize denuded areas.




Fig. 3

STA 12420+50: CFS maintenance needed.



Fig. 4

STA 12423+00 to 12426+00: Repair and restabilize denuded areas.

