

STANDARDS & SPECIFICATIONS COMPLAINT INVESTIGATION REPORT

Project Name:	Mountain Valley Pipeline (MVP)	S&S Program:	Mountain Valley Pipeline (SS027)			
Inspector:	Marshall Willis	Inspection Date:	Friday, March 28, 2025			
Project Contact:	Brian Clauto (EQT) Cory Chalmers (EQT)	Project Contact Email:	Cory.chalmers@eqt.com Brian.clauto@eqt.com			
Spread G: Montgomery County	STA 11668+00 - 11788+43	Site Conditions:	Dry			

Ш	Tree Felling		Clearing/Grubbing		Rough Grading		Trenching		Stri	nging/Welding
	Lowering/Backfilling		Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization	\boxtimes	Dor	mant
	the S&S	? ontrol n	neasures properly mai	ntained	cordance with the appr d in effective operating applicable, manufacture	condi	tion, in accordance	Yes	No	N/A
	3. Areas o	offsite	sediment deposition o	r unaut	thorized impacts to res	ource	s observed?		\boxtimes	
Background: This investigation was conducted in response to an email (IR#: 318192) on March 19, 2025. The email describes erosion occurring along MVPs temporary ROW resulting from the discharge of the permanent waterbars. Observations: 1. The ROW was stabilized with a combination of straw mulch, hydro-mulch and erosion matting. 2. Controls were installed and functioning properly. 3. One Corrective Action was noted during the inspection. 4. No areas of offsite sediment deposition were observed.										
	Comments: N/A				iication)					

<u>Deadline for Completion:</u> Within 72-Hour of Notification per S&S.

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Friday, March 28, 2025



STANDARDS & SPECIFICATIONS COMPLAINT INVESTIGATION REPORT

INSPECTION PHOTO LOG

Fig. 1 STA 11732+00: Restabilize denuded area.



Fig. 2
STA 11677+00: Controls installed and functioning properly.



Fig. 3 STA 11735+00: Controls installed and functioning properly.



Fig. 4
STA 11748+00: Controls installed and functioning properly.

