

## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

**LEVEL 1 (FIELD REPORT)** 

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Thursday, April 17, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cory.chalmers@eqt.com brian.clauto@eqt.com
Spread G: Giles County	STA 11326+85 - 11355+00 MVP-GI-256/256.02	Site Conditions:	Dry

ACT	CTIVE STAGE OF CONSTRUCTION: (Check all that apply)														
Ш	Tree Felling			Clearing/Grubbing		Rough Grading	Ш	Trenching		Stringing/Welding					
	Lowering/B	ackfilling		Final Grading		Temp. Stabilization	$\boxtimes$	Perm. Stabilization	$\boxtimes$	Doi	rmant				
									Yes	No	N/A				
	1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								$\boxtimes$						
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?									$\boxtimes$					
	3.	Areas of of	ffsite	sediment deposition ol	serve	d?				$\boxtimes$					
	Comments: Inspected the following resources: S-NN11 and S-NN12.  Routine Maintenance: (72-Hour Deadline from Notification) - STA 11331+00 to 11332+00: Restabilize denuded areas STA 11352+00: Restabilize denuded areas.  Ineffective Controls: (24-Hour Deadline from Notification) - N/A  Corrective Action: Maintain and install all controls per the approved S&S.														

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

Date: Thursday, April 17, 2025



## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

## FIELD INSPECTION PHOTO LOG

Fig. 1 **STA 11331+00 to 11332+00:** Restabilize denuded areas.



Fig. 2 **STA 11352+00:** Restabilize denuded areas.



Fig. 3 **MVP-GI-256.02:** Controls in place and functioning properly.



Fig. 4 STA 11346+00: Controls in place and functioning properly.

