

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Friday, April 25, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cory.chalmers@eqt.com brian.clauto@eqt.com
Spread I: Pittslyvania County	STA 15296+00 - 15370+62 MVP-PI-332	Site Conditions:	Dry

Tree Fellin	g		Clearing/Grubbing		Rough Grading		Trenching		Stri	nging/Weldin
Lowering/E	Backfilling		Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization	n 🖂	Dor	mant
								Yes	No	N/A
1.			alled and implemented I plan and stormwater		cordance with the approperation control contro	roved	erosion and	\boxtimes		
2.					d in effective operating applicable, manufactur				\boxtimes	
2	A				10				\boxtimes	
	<i>ent</i> s: Inspe	cted t	sediment deposition of		3, S-C4, S-H13 and W-	H5.				
Commo	ents: Inspe ne Maintena STA 1529 30 days p	cted to ance: 96+00 per MS 23+00	he following resources 1 to STA 15300+00: La S-18. 1 to STA 15333+19: La	s: S-C3		ultural			ECD'	
Commo	ents: Inspe ne Maintena STA 1529 30 days p STA 1532	cted to ance: 96+00 per MS 23+00 per MS	he following resources 1 to STA 15300+00: La S-18. 1 to STA 15333+19: La	s: S-C3	3, S-C4, S-H13 and W-	ultural			ECD'	
Commo	ents: Inspe ne Maintena STA 1529 30 days p STA 1532 30 days p ctive Contro	cted the control of t	he following resources 1 to STA 15300+00: La S-18. 1 to STA 15333+19: La	s: S-C3 andowr	3, S-C4, S-H13 and W-	ultural			ECD'	
Commo	ents: Inspe ne Maintena STA 1529 30 days p STA 1532 30 days p ctive Contro	cted the control of t	he following resources 1 to STA 15300+00: La S-18. 1 to STA 15333+19: La S-18.	s: S-C3 andowr	3, S-C4, S-H13 and W-	ultural			ECD'	

ensuring compliance on the above project.

Inspector Signature:

Date: Friday, April 25, 2025



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1

STA 15296+00 to STA 15300+00: Landowner has resumed agricultural activity. Remove damaged controls.



Fig. 2

STA 15296+00 to STA 15300+00: Landowner has resumed agricultural activity. Remove damaged controls.



Fig. 3

STA 15296+00 to STA 15300+00: Landowner has resumed agricultural activity. Remove damaged controls.



Fig. 4

STA 15296+00 to STA 15300+00: Landowner has resumed agricultural activity. Remove damaged controls.





STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 5

STA 15323+50 to STA 15333+19: Landowner has resumed agricultural activity. Remove damaged controls.



Fig. 6

STA 15323+50 to STA 15333+19: Landowner has resumed agricultural activity. Remove damaged controls.



Fig. 7

STA 15323+50 to STA 15333+19: Landowner has resumed agricultural activity. Remove damaged controls.



Fig. 8

STA 15323+50 to STA 15333+19: Landowner has resumed agricultural activity. Remove damaged controls.

