

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Tuesday, May 13, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cory.chalmers@eqt.com brian.clauto@eqt.com
Spread I: Franklin County	STA 13958+31 - 14000+00 MVP-FR-306.02	Site Conditions:	Rainy

<u>ACTI</u>	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling			Clearing/Grubbing		Rough Grading		Trenching		Strin	ging/Welding			
	Lowering/Backfilling			Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization	on \square Other		er			
									Yes	No	N/A			
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?													
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?													
	3.	Areas of of	fsite	sediment deposition o	bserve	d?				\boxtimes				
	Comments: Inspected the following resources: S-KL35, W-EF48 and S-KL36. Routine Maintenance: - STA 13958+00 to STA 13980+00: Landowner has resumed agricultural grazing activities. Remove ECD's within 30 days per MS-18. Ineffective Controls: - N/A Corrective Action: Remove damaged ECDs.													
Deadline: Various - See Comments The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project. Inspector Signature:														
Date	: Tuesda	ıy, May 13	3, 20	25										



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1

STA 13958+00 to STA 13980+00: Landowner has resumed agricultural activity. Remove damaged controls.



Fig. 2

STA 13958+00 to STA 13980+00: Landowner has resumed agricultural activity. Remove damaged controls.



Fig. 3

STA 13958+00 to STA 13980+00: Landowner has resumed agricultural activity. Remove damaged controls.



Fig. 4

STA 13958+00 to STA 13980+00: Landowner has resumed agricultural activity. Remove damaged controls.

