

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)			
Inspector:	Marshall Willis	Inspection Date:	Tuesday, May 27, 2025			
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cory.chalmers@eqt.com brian.clauto@eqt.com			
Spread H: Montgomery County Roanoke County	MVP-MLV-AR-28 MVP-RO-279.01 MVP-RO-281	Site Conditions:	Rainy			

ACT	CTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling		☐ Clearing/Grubbing			Rough Grading		Trenching		Stri	nging/Welding			
	Lowering/Backfilling			Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization	n 🗌 Other		er			
									Yes	No	N/A			
	1.	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							\boxtimes					
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?												
	3. Areas of offsite sediment deposition observed?								\boxtimes					
	Routin - Ineffec	ents: Inspective Maintena N/A ctive Contro N/A ctive Actio	nce: ols:	he following resources	s: N/A									
)ea	dline: N/A	Д												

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Tuesday, May 27, 2025



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 **STA 12635+00:** Controls in place and functioning properly.



Fig. 2

STA 12730+00: Controls in place and functioning properly.




Fig. 3 **STA 12464+00:** Controls in place and functioning properly.



Fig. 4

MVP-MLV-AR-28: Controls in place and functioning properly.

