

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Thursday, May 22, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cory.chalmers@eqt.com brian.clauto@eqt.com
Spread I: Franklin County	STA 14758+16 - 14845+68	Site Conditions:	Dry

<u>ACT</u>	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Felling		Clearing/Grubbing		Rough Grading		Trenching		Strin	ging/Welding			
	Lowering/Backfilling		Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization	Other		er			
								Yes	No	N/A			
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							\boxtimes					
	2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?												
	3. Areas of offsite sediment deposition observed?							\boxtimes					
 Comments: Inspected the following resources: S-MM44, S-MM45, S-MM48, S-H25, W-H9, S-H24, S-H23, S-A14, S-H and S-A13. Routine Maintenance: STA 14840+00: CFS undermined. Repair and restabilize. Ineffective Controls: N/A Corrective Action: Maintain and install all controls per the approved S&S. 										O-1 II 11			
The cons	titute non-compliaring compliance of	rective action on the above pro	deadline date applies to a rective actions are not copject.		ions noted on this report ι l by the deadline, other en								



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1

STA 14840+00: CFS undermined. Restabilize and repair rilling.



Fig. 2 **STA 14802+00:** Controls in place and functioning properly.



Fig. 3 STA 14821+00: Controls in place and functioning properly.



Fig. 4 STA 14831+00: Controls in place and functioning properly.

