

Mountain Valley Pipeline

Project Name:

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

S&S Program:

Mountain Valley Pipeline (SS027)

Inspector:	Matthew Grant, Marshall Willis, Zack Robinson	Inspection Date:	Tuesday, June 3, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cory.chalmers@eqt.com brian.clauto@eqt.com
Spread H: Montgomery County Franklin County	MVP-MN-268 STA 12007+00 – STA 12072+84 MVP-MN-270 STA 13012+63 – STA 13033+59 MVP-FR-289	Site Conditions:	Dry
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)			
☐ Tree Felling	☐ Clearing/Grubbing ☐ Rough	gh Grading 🔲 Trench	ing Stringing/Welding
☐ Lowering/Backfilling	☐ Final Grading ☐ Tem	p. Stabilization 🗵 Perm.	Stabilization
			Yes No N/A
1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?			
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?			
3. Areas of	offsite sediment deposition observed?		
Comments: Inspected the following resources: S-G36, S-G39, S-PP23, S-G40, S-G24. S-G23 and W-ST2. Routine Maintenance:			
Deadline: Within 72-Hour of Notification The recommended corrective action deadline data applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently			

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Tuesday, June 3, 2025



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 STA 13023+50: Remove/repair damaged controls.



Fig. 2

STA 13023+00: Controls in place and functioning properly.



Fig. 3 **STA 12070+00:** Controls in place and functioning properly.



Fig. 4

STA 12039+00: Controls in place and functioning properly.

