

## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

**LEVEL 1 (FIELD REPORT)** 

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Thursday, June 5, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cory.chalmers@eqt.com brian.clauto@eqt.com
Spread I: Franklin County	STA 13690+91 - 13784+35 MVP-FR-300	Site Conditions:	Dry

<u>ACT</u>	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling	g		Clearing/Grubbing		Rough Grading		Trenching		Strin	nging/Welding			
	Lowering/B	Lowering/Backfilling		Final Grading	Grading 🔲 Temp. Stabilization 🗵 Perm. Stabilizati		Perm. Stabilization		Othe	er				
									Yes	No	N/A			
	1.	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?												
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?												
	3.	3. Areas of offsite sediment deposition observed?								$\boxtimes$				
Routine Maintenance (72-Hr):  - MVP-FR-300: Remove damaged controls piled of ROW by landowner.  Ineffective Controls (24-Hr):  - N/A  Corrective Action: Maintain and install all controls per the approved S&S.														
The reconst	ecommended itute non-compling compliance	corrective ac pliance and/c e on the abo	ction de or corre ve pro	ective actions are not con ject.		ions noted on this report υ l by the deadline, other en								



## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

## FIELD INSPECTION PHOTO LOG

Fig. 1 MVP-FR-300: Remove damaged controls off LOD.



Fig. 2 **Stream S-EF54:** Controls in place and functioning properly.



Fig. 3 **STA 13705+00:** Controls in place and functioning properly.



Fig. 4
STA 13775+00: Controls in place and functioning properly.

