

### **STANDARDS & SPECIFICATIONS** SITE INSPECTION REPORT

**LEVEL 1 (FIELD REPORT)** 

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Wednesday, June 4, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cory.chalmers@eqt.com brian.clauto@eqt.com
Spread I: Franklin County	STA 14222+00 - 14249+19 MVP-MLV-AR-32 MVP-FR-311	Site Conditions:	Dry

7	Γree Fellin	g		TION: (Check all that a		Rough Grading		Trenching		Strii	nging/Welding
Lowering/Bac		ackfilling		Final Grading		Temp. Stabilization	$\boxtimes$	Perm. Stabilization	n 🗆 Other		er
									Yes	No	N/A
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								$\boxtimes$		
	2.	2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								$\boxtimes$	
	<ol> <li>Areas of offsite sediment deposition observed?</li> </ol>								$\boxtimes$		
	Routin - - Ineffec	e Maintena STA 1423 STA 1423 tive Contro	nce ( 2+00 2+00 ols (2 2+50	to 14746+00: Restabi :: Restabilize perm. WE 4-Hr): :: CFS undermined abo	lize de 3. ove S-						

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

Date: Wednesday, June 4, 2025



## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

#### FIELD INSPECTION PHOTO LOG

Fig. 1 STA 14232+50: CFS undermined. Restabilize and repair rilling.




Fig. 2 **STA 14232+50:** CFS undermined. Restabilize and repair rilling.



Fig. 3 **STA 14237+00 to 14246+00:** Restabilize denuded areas.



Fig. 4 **STA 14237+00 to 14246+00:** Restabilize denuded areas.





# STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

#### FIELD INSPECTION PHOTO LOG

