

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Matthew Grant	Inspection Date:	Monday, June 2, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	Cory.chalmers@eqt.com Brian.clauto@eqt.com
Spread G: Giles County	STA 11060+75-10930 MLV 25	Site Conditions:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	☐ Tree Felling		☐ Clearing/Grubbing		☐ Rough Grading		☐ Trenching			Stringing/Welding		
	Lowering/Backfilling			Final Grading		Temp. Stabilization	n 🏻 Perm. Stabilizatio		\boxtimes	Dormar	nt	
	1.					cordance with the appr	oved	erosion and	Yes	No N/	_	
	2.	Are all control measures properly maintained in effective operating condition in accordance]	
	3.	Areas of offsite sediment deposition observed?]	
	Comments: Inspected the following resources: S-IJ 16b, S-IJ 18, S-RR5, S-E25, S-E24, S-Y4, S-Y2 Routine Maintenance: (72-Hour Deadline from Notification) - STA 12050 to 11053: Repair erosion and restabilize denuded areas. - STA 121045+67: Repair erosion and restabilize denuded areas. Ineffective Controls: (24-Hour Deadline from Notification) - STA 11051+50: Repair undermined P1 silt fence and maintain the CFS downslope Corrective Action: Maintain and install all controls per the approved S&S.											
The re		corrective a	ction de	eadline date applies to al ective actions are not cor		ions noted on this report u by the deadline, other en						
Inspector Signature:												
Date	· Monda	ov. June 2	202	5								



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG



Fig. 2 STA 11053-11051+29: Repair and restabilize denuded areas.



Fig. 3 STA 11051+50: P1 maintenance needed.



Fig. 4 STA 11051+50: CFS maintenance required.

