



# STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

|                                |  |                        |   |
|--------------------------------|--|------------------------|---|
| Project Name:                  | Mountain Valley Pipeline                 | S&S Program:           | Mountain Valley Pipeline (SS027)              |
| Inspector:                     | Marshall Willis                          | Inspection Date:       | Thursday, June 12, 2025                       |
| Project Contact:               | Cory Chalmers<br>Brian Clauto            | Project Contact Email: | cory.chalmers@eqt.com<br>brian.clauto@eqt.com |
| Spread G:<br>Montgomery County | STA 11696+94 – 11618+91<br>MVP-MN-258.05 | Site Conditions:       | Dry   |

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling      ☐ Clearing/Grubbing      ☐ Rough Grading      ☐ Trenching      ☐ Stringing/Welding
- ☐ Lowering/Backfilling      ☐ Final Grading      ☐ Temp. Stabilization      ☒ Perm. Stabilization      ☐ Other

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: SOO6, S-RR13 and S-RR14.

**Routine Maintenance (72-Hr):**

- STA 11618+00 to 11618+50: Restabilize area.

**Ineffective Controls (24-Hr):**

- N/A

**Corrective Action:** N/A

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Thursday, June 12, 2025

# STANDARDS & SPECIFICATIONS

## SITE INSPECTION REPORT

### LEVEL 1 (FIELD REPORT)

### FIELD INSPECTION PHOTO LOG

Fig. 1

**STA 11618+00 to 11618+50:** Restabilize denuded areas.



Fig. 2

**STA 11618+00 to 11618+50:** Restabilize denuded areas.



Fig. 3

**Stream S-RR14:** Controls in place and functioning properly.



Fig. 4

**STA 11614+00:** Controls in place and functioning properly.

