

## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

| LEVEL 1 (FIELD REPORT) |
|------------------------|
|------------------------|

| Project Name:                  | Mountain Valley Pipeline         | S&S Program:           | Mountain Valley Pipeline (SS027)              |
|--------------------------------|----------------------------------|------------------------|---|
| Inspector:                     | Matthew Grant                    | Inspection Date:       | Wednesday, July 16, 2025                      |
| Project Contact:               | Cory Chalmers<br>Brian Clauto    | Project Contact Email: | Cory.chalmers@eqt.com<br>Brian.clauto@eqt.com |
| Spread H:<br>Montgomery County | STA 12072-12010<br>MN270, 268.01 | Site Conditions:       | Dry   |

| ACT | ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)  |  |                     |  |  |               |  |           |             |             |               |  |  |  |
|-----|---|--|---------------------|--|--|---------------|--|-----------|-------------|-------------|---------------|--|--|--|
|     | Tree Felling  |  | ☐ Clearing/Grubbing |  |  | Rough Grading |  | Trenching |             | Stri        | nging/Welding |  |  |  |
|     | Lowering/B  | owering/Backfilling $\square$ Final Grading $\square$ Temp. Stabilization $oxtimes$ Perm. Stabilizatio |                     |  |  |               |  | Dor       | mant        |             |               |  |  |  |
|     |   |  |                     |  |  |               |  |           | Yes         | No          | N/A           |  |  |  |
|     | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?   |  |                     |  |  |               |  |           |             |             |               |  |  |  |
|     | <ol> <li>Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?</li> <li>Areas of offsite sediment deposition observed?</li> </ol>                                       |  |                     |  |  |               |  |           | $\boxtimes$ |             |               |  |  |  |
|     |   |  |                     |  |  |               |  |           |             | $\boxtimes$ |               |  |  |  |
|     | Comments: Inspected the following resources: S-G40, S-G39. S-G38  Routine Maintenance: (72-Hour Deadline from Notification) - STA 12315: Repair ECM  Ineffective Controls: (24-Hour Deadline from Notification) - N/A  Corrective Action: Maintain and install all controls per the approved S&S. |  |                     |  |  |               |  |           |             |             |               |  |  |  |
|     |   |  |                     |  |  |               |  |           |             |             |               |  |  |  |

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Wednesday, July 16, 2025



## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

## FIELD INSPECTION PHOTO LOG

Fig. 1

STA 12072: Stabilization and ECD remains in place.



Fig. 2

Designated Crossing S-G40: ECD's remain in place.



Fig. 3

**Designated Crossing S-G39:** ECD's remain in place.



Fig. 4

**Designated Crossing S-G38:** ECD's remain in place.

