

COMPLAINT INVESTIGATION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis, Matthew Grant
Inspection Date:	Tuesday, July 15, 2025	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13888+00 – STA 13916+00	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☒ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☒ Perm. Stabilization
 ☐ Other

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Background: This investigation was conducted in response to complaint (IR#: 319764) submitted to PREP on July 14, 2025. The incident describes “heavy stream sedimentation” and “work on the MVP causing heavy red mud to be released to the creek”.

Observations:

1. MVP is completing install of full length permanent waterbars from 13889+00 to 13892+00 and was stabilizing slope with matting and removing the RCE at the time of inspection.
2. MVP is starting bank repair to S-II2 at STA 13915+00 and has opened a travel lane from Iron Ridge Road to S-II2 (STA 13892+00 to 13915+00). In-stream work had not started at the time of inspection.
3. No impacts were observed to S-II2 or Little Creek from the MVP ROW.
4. Controls were in place and functioning properly at the time of inspection
5. No additional sediment discharged off ROW was found during the inspection.

Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, July 15, 2025

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, July 15, 2025

Figure 1: STA 13891+00 – Full length waterbars installed and stabilized with erosion control matting.



Figure 2: STA 13898+00 – Travel lane installed for access to S-II2 bank repair. Controls in place and functioning properly.



Figure 2: STA 13907+00 – Travel lane installed for access to S-II2 bank repair. Controls in place and functioning properly.



Figure 4: Stream S-II2 – Little Creek at the MVP crossing. No work was being done in the stream. Note turbid condition of the stream. Controls in place and functioning properly.

