

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Thursday, July 31, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cory.chalmers@eqt.com brian.clauto@eqt.com
Spread I: Franklin County	STA 14250+00 - 14311+57 MVP-FR-313	Site Conditions:	Wet

Tree Fellin			TION: (Check all that a	\boxtimes	Rough Grading		Trenching		Stri	nging/Welding
Lowering/E	Backfilling		Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization		Oth	ner
								Yes	No	N/A
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes		
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes		
3.	Areas of o	ffsite	sediment deposition of	serve	d?				\boxtimes	
Routin - Ineffec - -	e Maintena N/A ctive Contro STA 1429 STA 1429	ance (ols (2 95+00 95+00	4-Hr): b: Stabilize stockpile. b: Repair undermined (OFS.	A, S-F10 and S-F9B.	ed S&	S.			

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Thursday, July 31, 2025



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 **STA 14295+00:** Stabilize stockpile.



Fig. 2 STA 14295+00: Repair undermined CFS.



Fig. 3 STA 14295+00: Repair undermined CFS.



Fig. 4 STA 14295+00: Repair undermined CFS.

