

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Matthew Grant	Inspection Date:	Thursday, August 14, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	Cory.chalmers@eqt.com Brian.clauto@eqt.com
Spread H: Montgomery County	MLV 28 MN 279, MLV AR 28	Site Conditions:	Dry

	CTIVE CTACE OF CONCEDUCTION. (Check all that apply)														
<u>ACT</u>	CTIVE STAGE OF CONSTRUCTION: (Check all that apply)														
	Tree Felling		☐ Clearing/Grubbing			Rough Grading		Trenching		Stringing/Welding					
	Lowering/Back	wering/Backfilling \square Final Grading \square Temp. Stabilization $oxtimes$ Perm. St		Perm. Stabilization		Dor	mant								
									Yes	No	N/A				
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes						
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes						
	3. Are	eas of offs	ite s	sediment deposition o	bserve	d?				\boxtimes					
	Comments: Inspected the following resources: S-CD12Bb Routine Maintenance: (72-Hour Deadline from Notification) - MLV AR28: restabilize per spec MVP ES33.1 Ineffective Controls: (24-Hour Deadline from Notification) - N/A Corrective Action: Maintain and install all controls per the approved S&S.														

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Thursday, August 14, 2025



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 MLV 28: Portions of the area have been mulched.



Fig. 2 MLV AR 28: Center strip requires maintenance.



Fig. 3 MLV AR 28: Center strip requires maintenance.



Fig. 4

MLV AR 28: Center strip requires maintenance.

