

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Matthew Grant	Inspection Date:	Wednesday, August 6, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	Cory.chalmers@eqt.com Brian.clauto@eqt.com
Spread G: Giles County	STA 11205-11254, 11170-11165 MLV AR025 ATWS 1347, 1370	Site Conditions:	Rainy

<u>ACTI</u>	VE STAGE	OF CONST	<u> </u>	TION: (Check all that	apply)						
	Tree Fellin	g		Clearing/Grubbing		Rough Grading		Trenching		Strir	nging/Welding
	Lowering/E	Backfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	n 🗵 Dormant		
									Yes	No	N/A
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							\boxtimes			
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes	
	3. Areas of offsite sediment deposition observed?								\boxtimes		
	Comments: Inspected the following resources: S-YZ6, S-RR2, W-RR1B Routine Maintenance: (72-Hour Deadline from Notification) - STA 11230 restabilize denuded area STA 11250 restabilize denuded area. Ineffective Controls: (24-Hour Deadline from Notification) - STA 11240 reinstall perimeter control Corrective Action: Maintain and install all controls per the approved S&S.										
Deadline: Various - See Comments The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project. Inspector Signature: Date: Wednesday, August 6, 2025											



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 STA 111240: reinstall perimeter control.



Fig. 2 STA11250: Restabilize denuded area.



Fig. 3 **STA 11250**: restabilize denuded area.



Fig. 4

STA 11230: restabilize denuded area.

