



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Matthew Grant	Inspection Date:	Tuesday, August 5, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	Cory.chalmers@eqt.com Brian.clauto@eqt.com
Spread G: Giles County	STA 11354-11254 GI 253.02, 256 ATWS 633A	Site Conditions:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling ☐ Clearing/Grubbing ☐ Rough Grading ☐ Trenching ☐ Stringing/Welding
☐ Lowering/Backfilling ☐ Final Grading ☐ Temp. Stabilization ☐ Perm. Stabilization ☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-NN12, S-NN11, S-MM18, W-RR1B

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 11275 restabilize denuded area.
- STA 11260 repair erosion and restabilize area.
- STA 11262 waterbar requires maintenance along flow path and stabilization.

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 11291 undermined CFS requires repair/reinstall.
- STA 11329-11330. ATWS 633A: undermined P1 requires repair/reinstall.

Corrective Action: Maintain and install all controls per the approved S&S.

Deadline: Various - See Comments

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Tuesday, August 5, 2025

STANDARDS & SPECIFICATIONS

SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1
Near STA 11329: P1 is undermined.



Fig. 2
STA 11330: CFS requires maintenance.



Fig. 3
Near STA 11330: rill erosion has occurred.



Fig. 4
STA 11330: P1 is undermined.



STANDARDS & SPECIFICATIONS

SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 5

ATWS 633A: P1 is undermined.



Fig. 6

Near Sta 11291: CFS is undermined.



Fig. 7

STA 11275: denuded area requires additional stabilization.



Fig. 8

Near STA 11262: waterbar requires maintenance.



STANDARDS & SPECIFICATIONS

SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 9
STA 10816: ongoing installation of permanent waterbars.



Fig. 10
STA 11325: ECD's remain in place.



Fig. 11
Designated Crossing W-RR1B: upland ECD's remain in place.



Fig. 12
Designated Crossing S-NN12: ECD's remain in place.

