

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, August 7, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County Franklin County	STA 13316+13 – 13300+00 STA 12994+00 – 13012+63 STA 12687+00 – 12705+00	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-GH7.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Friday, August 7, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, August 7, 2020

Figure 1: STA 13315+00 – Controls in place and functioning properly.

☼ 266°W (T) ● 37°3'33"N, 80°3'20"W ±12385ft ▲ 1321ft



Figure 2: STA 13506+00 – Controls in place and functioning properly.

☼ 9°N (T) ● 37°6'25"N, 80°3'19"W ±32ft ▲ 1414ft



Figure 3: STA 13011+00 – Controls in place and functioning properly along the Blue Ridge Parkway.

☼ 315°NW (T) ● 37°7'33"N, 80°7'31"W ±16ft ▲ 2677ft



Figure 4: STA 12694+00 – Controls in place and functioning properly. Area stabilized with erosion matting and Earth Guard.

☼ 126°SE (T) ● 37°11'28"N, 80°9'24"W ±16ft ▲ 3724ft

