

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, July 30, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12373+28 – 12435+16 ATWS 724/1507/1506/726/725 MVP-MN-279/279.02 MVP-MLV-AR-27	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-OO16, S-NN19, W-NN8 and S-NN16.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, July 30, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, July 30, 2020

Figure 1: STA 12420+00 – Controls in place and functioning properly.

⊗ 6°N (T) ● 37°14'12"N, 80°11'58"W ±98ft ▲ 1206ft



Figure 2: STA 12410+00 – Controls in place and functioning properly.

⊗ 308°NW (T) ● 37°14'20"N, 80°11'58"W ±8645ft ▲ 1358ft



Figure 3: STA 12385+00 – Controls in place and functioning properly.

⊗ 296°NW (T) ● 37°14'36"N, 80°12'21"W ±32ft ▲ 1409ft



Figure 4: Stream S-NN19 – Controls in place and functioning properly around stream crossing.

⊗ 338°NW (T) ● 37°14'38"N, 80°12'25"W ±16ft ▲ 1339ft

