

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, July 28, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12001+00 – 12036+00 ATWS 473/473A/474/474A MVP-MN-268/268.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G36, S-G38, S-G39, S-G40 and S-PP23.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, July 28, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, July 28, 2020

Figure 1: STA 12036+00 – Controls in place and functioning properly.

☼ 123°SE (T) ● 37°17'40"N, 80°17'13"W ±28242ft ▲ 1684ft



12036

Figure 2: STA 12033+00 – Controls in place and functioning properly.

☼ 286°W (T) ● 37°15'52"N, 80°18'29"W ±16ft ▲ 1786ft



12033

Figure 3: Stream S-G38 – Controls in place and functioning properly around stream crossing.

☼ 128°SE (T) ● 37°16'2"N, 80°18'47"W ±32ft ▲ 1649ft



S-G38

Figure 4: ATWS 473 – Controls in place and functioning properly.

☼ 266°W (T) ● 37°16'9"N, 80°18'47"W ±32ft ▲ 1619ft



Atws 473