

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, September 11, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12071+80 – 12119+17 ATWS 1162/1163 MVP-MN-270	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-MM15, S-MM14, S-MM13, S-MM11, S-F15, W-F9-PFO and S-F16a/b.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Friday, September 11, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, September 11, 2020

Figure 1: STA 12072+00 – Controls in place and functioning properly.

☉ 331°NW (T) ☉ 37°15'30"N, 80°17'51"W ±16ft ▲ 1858ft



12072

Figure 2: Stream S-MM15 – Controls in place and functioning properly around stream S-MM15 crossing.

☉ 75°E (T) ☉ 37°15'30"N, 80°17'48"W ±16ft ▲ 1780ft



S-MM15

Figure 3: STA 12105+00 – Controls in place and functioning properly.

☉ 94°E (T) ☉ 37°15'30"N, 80°17'13"W ±16ft ▲ 1494ft



12105

Figure 4: STA 12116+00 – Controls in place and functioning properly.

☉ 146°SE (T) ☉ 37°15'27"N, 80°17'0"W ±32ft ▲ 1459ft



12116