

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, September 9, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14800+00 – 14817+20 STA 14751+50 – 14776+65 MVP-FR-323/322	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-H23, S-HH1, S-A22, S-MM44 and S-MM45.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, September 9, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, September 9, 2020

Figure 1: STA 14761+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 121°SE (T) ☉ 36°59'0"N, 79°41'23"W ±328ft ▲ 958ft



Figure 2: STA 14802+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 114°SE (T) ☉ 36°58'36"N, 79°40'41"W ±16ft ▲ 944ft



Figure 3: Stream S-HH1 – Controls in place and functioning properly around stream S-HH1 crossing.

☉ 293°W (T) ☉ 36°58'29"N, 79°40'27"W ±16ft ▲ 921ft



Figure 4: STA 14815+75 – Unauthorized offsite LDA impacting perimeter MVP controls. Controls being repaired.

☉ 118°SE (T) ☉ 36°58'29"N, 79°40'28"W ±32ft ▲ 918ft

