

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, September 1, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12373+76 – 12422+32 MVP-MN-279.02 ATWS 724	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-NN19 and S-OO16.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, September 1, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, September 1, 2020

Figure 1: STA 12421+00 – Controls in place and functioning properly. Area stabilized with erosion matting and straw.

⊗ 15°N (T) ● 37°14'18"N, 80°12'52"W ±22218ft ▲ 1039ft



12421

Figure 2: STA 12400+00 – Controls in place and functioning properly. Area stabilized with erosion matting and straw.

⊗ 322°NW (T) ● 37°14'29"N, 80°12'6"W ±5111ft ▲ 1475ft



12400

Figure 3: STA 12385+00 – Controls in place and functioning properly. Area stabilized with erosion matting and straw.

⊗ 321°NW (T) ● 37°14'35"N, 80°12'20"W ±98ft ▲ 1442ft



12385

Figure 4: STA 12377+00 – Controls in place and functioning properly. Area stabilized with erosion matting and straw.

⊗ 300°NW (T) ● 37°14'33"N, 80°12'38"W ±13589ft ▲ 1326ft



12377