

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, August 28, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12422+00 – 12443+12 MVP-MN-279 ATWS 727/726/725/1506/1507	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-NN16.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Friday, August 28, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, August 28, 2020

Figure 1: Stream S-NN16 – Controls in place and functioning properly around stream S-NN16.

☉ 26°NE (T) ☉ 37°13'59"N, 80°11'52"W ±16ft ▲ 1181ft



Figure 2: STA 12442+00 – Controls in place and functioning properly.

☉ 223°SW (T) ☉ 37°13'59"N, 80°11'54"W ±16ft ▲ 1188ft



Figure 3: STA 12447+00 – Controls in place and functioning properly.

☉ 325°NW (T) ☉ 37°13'54"N, 80°11'55"W ±16ft ▲ 1219ft



Figure 4: STA 12424+00 – Controls in place and functioning properly.

☉ 143°SE (T) ☉ 37°14'9"N, 80°11'58"W ±16ft ▲ 1178ft

