

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, August 19, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12102+69 – 12119+17 STA 12153+28 – 12190+81 MVP-MN-270.01/273/274	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-F15, S-16a/b, S-C25 and S-C24.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, August 19, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, August 19, 2020

Figure 1: STA 12105+00 – Controls in place and functioning properly.

☉ 108°E (T) ☉ 37°15'30"N, 80°17'14"W ±1187ft ▲ 1531ft



Figure 2: STA 12114+00 – Controls in place and functioning properly.

☉ 105°E (T) ☉ 37°14'2"N, 80°15'40"W ±9843ft ▲ 1452ft



Figure 3: STA 12156+00 – Controls in place and functioning properly.

☉ 108°E (T) ☉ 37°14'13"N, 80°15'40"W ±6076ft ▲ 1537ft



Figure 4: Stream S-C24 – Controls in place and functioning properly around S-C24 crossing.

☉ 74°E (T) ☉ 37°13'56"N, 80°15'31"W ±6076ft ▲ 1396ft

