

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, October 20, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12975+00 – 12964+00 MVP-RO-288	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-KL4.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, October 20, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, October 20, 2020

Figure 1: STA 12973+00 – Controls in place and functioning properly.

☼ 141°SE (T) ● 37°7'38"N, 80°7'57"W ±213ft ▲ 2691ft



Figure 2: STA 12969+00 – Controls in place and functioning properly.

☼ 156°SE (T) ● 37°7'44"N, 80°8'16"W ±213ft ▲ 2695ft



Figure 3: STA 12968+00 – Controls in place and functioning properly.

☼ 28°NE (T) ● 37°7'54"N, 80°8'15"W ±16ft ▲ 2812ft



Figure 4: MVP-RO-288 – Controls in place and functioning properly at S-KL4 crossing.

☼ 158°SE (T) ● 37°7'57"N, 80°7'55"W ±16ft ▲ 2615ft

