

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, October 14, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13415+51 – 13438+31 ATWS 1343/1342/1351 MVP-FR-293.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-IJ4.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, October 14, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, October 14, 2020

Figure 1: STA 13417+00 – Controls in place and functioning properly. Area stabilized with erosion matting and Earth Guard.

☉ 288°W (T) ☉ 37°5'31"N, 80°1'35"W ±32ft ▲ 1472ft



Figure 2: Stream S-IJ4 – Controls in place and functioning properly around S-IJ4 crossing.

☉ 119°SE (T) ☉ 37°5'29"N, 80°1'28"W ±32ft ▲ 1438ft



Figure 3: MVP-FR-293.02 – Secondary containment in place and functioning properly.

☉ 227°SW (T) ☉ 37°5'26"N, 80°1'12"W ±16ft ▲ 1711ft



Figure 4: STA 13439+00 – PPL actively working to replace CFS in area.

☉ 127°SE (T) ☉ 37°5'27"N, 80°0'22"W ±223ft ▲ 1335ft

