

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, September 30, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12119+17 – 12140+00 STA 12187+00 – 12200+00 MVP-MN-274/275	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-C36, W-C12, S-C33, W-C11, S-MM31, W-C8, S-C29, S-C21 and S-OO11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Wednesday, September 30, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, September 30, 2020

Figure 1: STA 12120+00 – Controls in place and functioning properly.

☼ 111°E (T) ● 37°15'33"N, 80°16'50"W ±213ft ▲ 1454ft



12120

Figure 2: STA 12131+00 – Controls in place and functioning properly. Area stabilized with straw and erosion matting.

☼ 95°E (T) ● 37°15'23"N, 80°16'42"W ±16ft ▲ 1376ft



12131

Figure 3: STA 12188+00 – Controls in place and functioning properly. Area stabilized with straw.

☼ 290°W (T) ● 37°15'8"N, 80°15'36"W ±16ft ▲ 1276ft



12188

Figure 4: MVP-MN-275 – Controls in place and functioning properly.

☼ 327°NW (T) ● 37°15'7"N, 80°15'30"W ±16ft ▲ 1241ft



MN-275