

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, September 28, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14062+17 – 14171+36 ATWS 1472/1473/1478/1479/1480	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-EF48, W-EF51, S-KL61, S-KL41, S-C8 and S-KL51.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, September 28, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, September 28, 2020

Figure 1: STA 14065+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 69°E (T) ☉ 37°3'50"N, 79°52'30"W ±213ft ▲ 1193ft



Figure 2: STA 14082+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 90°E (T) ☉ 37°3'53"N, 79°52'10"W ±16ft ▲ 1193ft



Figure 3: STA 14104+00 – Controls in place and functioning properly. Area stabilized with straw and erosion matting.

☉ 76°E (T) ☉ 37°3'44"N, 79°51'47"W ±16ft ▲ 1044ft



Figure 4: STA 14155+00 – Controls in place and functioning properly. Area stabilized with straw and erosion matting.

☉ 106°E (T) ☉ 37°3'23"N, 79°51'4"W ±16ft ▲ 1022ft

